Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/11011ME-0142

Work Order Type:

Audit Name: 11011ME-0142

CLIENT INFORMATION

Client Name: NA Address:

Client ID: 11011ME-0142

Alt. Client ID: LOUDON

CLIENT CONTACT INFORMATION

NA

AGENCY INFORMATION

Agency: Mid-East Community Action Agency Agency Phone: (865) 248-8661

Address: P. O. Box 790

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Auditor - Kevin Human PH # 865-405-4386 Date - 3/19/10 Home Type - Site Built Primary Heat - Elec.

Measure 1 Inf	iltration Redctn			Componen	its			Inspected
INSTA ONLY	A3 REPLACE BROKEN PA LL APPROX. 22" X 18" FI A GRATE WITH NO PLAC IR RETURN PLENUM APF	LTER RE	TURN ILTER	- CURRENT IN ENTIRE	LY THEF			
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Comment HEAT	NE UP FURANCE IS NOT WORKING PROF IS APPROX 1284 SQ. FT			Componen		ACE		Inspected
Comment HEAT HOME	IS NOT WORKING PROF IS APPROX 1284 SQ. FT	Γ.		Estimated	<u> </u>		Actual	
Comment HEAT HOME	IS NOT WORKING PROP		Qty 1	-		ACE Qty		Inspected
Comment HEAT HOME # Material / Labor 1 Heating	IS NOT WORKING PROF	Γ. <i>Unit</i> s	Qty	Estimated	<u> </u>		Actual	
Comment HEAT HOME # Material / Labor 1 Heating Equipment	IS NOT WORKING PROF IS APPROX 1284 SQ. FT Description / Comment TUNE UP FURNACE	Г. <i>Units</i> Each	Qty 1	Estimated	<u> </u>		Actual	
Comment HEAT HOME # Material / Labor 1 Heating Equipment 2 Labor	IS NOT WORKING PROF IS APPROX 1284 SQ. FT Description / Comment TUNE UP FURNACE	Г. <i>Units</i> Each	Qty 1	Estimated	<u> </u>		Actual	
Comment HEAT HOME # Material / Labor 1 Heating Equipment 2 Labor	IS NOT WORKING PROF IS APPROX 1284 SQ. FT Description / Comment TUNE UP FURNACE	Г. <i>Units</i> Each	Qty 1	Estimated	<u> </u>		Actual	
Comment HEAT HOME # Material / Labor 1 Heating Equipment 2 Labor	IS NOT WORKING PROF IS APPROX 1284 SQ. FT Description / Comment TUNE UP FURNACE	Units Each Each	Qty 1 1	Estimated	<u> </u>	Qty	Actual	

Report Run On: 5/25/2010

Measure 3 DV	VH Tank Insulation			Componen	ts			Inspecte
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
Macaura 4 Di	VIII Dina Inquiation			Company	40			Inspecto
	VH Pipe Insulation			Componen	ts			Inspecte
	VH Pipe Insulation			Componen Estimated			Actual	Inspecte
Measure 4 DV Comment # Material / Labor	VH Pipe Insulation Description / Comment	Units	Qty	•		Qty		Inspecte
Comment # Material / Labor	-	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor	Description / Comment			Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation			Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated		Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated		Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated		Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated			Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated Unit Cost			Actual Unit Cost	

Report Run On: 5/25/2010

Measure 5 Fix	Improper Venting (Cloth	hes Dryer)	Componen	ts		1	nspected
	ement by Linear Foot. ND DRYER HOSE. EXTER	ND DRYE	R VEN	T APPROX	12'.			
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	y Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 6 We	atherstrip Door D2			Componen				Inspected
Comment	•	Unio		Estimated	1		Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected
Comment	•	Units		Estimated	1	Qty	Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
# Material / Labor 1 Doors	Description / Comment Weatherstrip D2	Units	Qty 1	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Doors2 Labor	Description / Comment Weatherstrip D2	Units	Qty 1	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Doors2 Labor	Description / Comment Weatherstrip D2	Units	Qty 1	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Doors2 Labor	Description / Comment Weatherstrip D2		Qty 1 1	Estimated	1		Actual	
Comment# Material / Labor1 Doors2 Labor	Description / Comment Weatherstrip D2		Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Doors 2 Labor Other Detail	Description / Comment Weatherstrip D2		Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 5/25/2010

Measure 7 Mastic 8 Registers @ Floor				Componen	ts	Inspected		
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Other	Mastic 8 Registers @ Floor		8					
2 Labor	Labor		1					
Other Detail			1			,		
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
		Work O	rder Gra	and Total:		Gran	d Total:	